



- G - Motor Positive
- H - +5V
- I - Reference
- J - OV
- K - Motor Negative
- P - 0V
- Q - +1.2V (ish)
- R - +5V